

Work Order ID 76517***76517***

Page 1

November-16-11 12:02:37 PM

Item ID: D2661-2

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Saddle, RH Fwd Aft Out 206

Start Date: 11/16/11 Start Qty: 4.00

4

Cust Item ID:

Required Date: 11/17/11 Req'd Qty: 4.00

4

Customer: CU-DAR001

Reference: RMA RA111291 - RETURN

Approvals: Process Plan: 

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

D2661	Rev D
-------	-------

100

0.00

100

QC

Quality Control

Memo

INSPECT RA111291

0.00

110

0.00

110

Packaging

Packaging

Memo

RE-IDENTIFY USING NEW B/N

0.00

120

QC21- Final Inspection - Work Order Release

0.00

120

QC

Quality Control

Memo

0.00

8 u/u/18
B74775 (24)

11/17/11 SD (4)

11/17/11

R(11-11-17)

Picklist Print

November-16-11 12:02:37 PM

Page 1

Work Order ID: 76517

Parent Item: D2661-2

Parent Item Name: Saddle, RH Fwd Aft Out 206

Start Date: 11/16/11

Required Date: 11/17/11

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP: C00.11.01Removed P/O for Powder Coat - in house processEC
IPP Rev:D As per Rev D 07-03-19 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2661-2		Manufactured	No				Each	11.0000		4			
Saddle, RH Fwd Aft Out 206													

Location

Loc Qty

Loc Code

ST476

11

73842

1

75117

10

74475

4

h

RA 1 291 D266 / D2662

SADDLES
NCR11-935

Received @ Dart November 11th, 2011
Inspected @ Dart November 16th, 2011

Instructions for RA 111291 D2661/D2662 Saddles

- Qty X 34 saddles were returned
- Following are to be SCRAPED**
 - D2662-2 B11028 QTY X 4, B9043 QTY X 2, B9042 QTY X 3
 - D2661-1 B64559 QTY X 5
 - D2661-2 B9913 QTY X 1, B10476 QTY X 3, B10015 QTY X 1, B10016 QTY X 1
- Need a work order to scrap
- Following are to be returned to STOCK**
 - D2662-2 B74482 QTY X 1, B74484 QTY X 1, B75118 QTY X 1
 - D2662-1 B73846 QTY X 2
 - D2661-1 B73839 QTY X 4
 - D2661-2 B74475 QTY X 4
- Need a separate work order for each model to return back in to stock

- D2662-2 B74483 was dropped by DS needs to be striped then assed by QC and if not damaged to be re powder coated and put back in to stock under a new

BATCH #

Keep

✓ 76516 - D2661-1	4	73839
✓ 76517 - D2661-2	4	74475
✓ 76518 - D2662-1	2	73846
✓ 76519 - D2662-2	3	1-74482 1-74484 1-75118

Scrap

5	-64559
6	1-9913 3-10476 1-10015 1-10016
7	
8	
9	4-11028 2-9043 3-10012

76520 ✓
76521 ✓

